

**Communicator e3000
MPE/iX Release 7.5 PowerPatch 3
(Software Release C.75.03)**

HP e3000 MPE/iX Computer Systems

Volume 13, Issue 4



**Manufacturing Part Number : 30216-90361
E0706**

U.S.A. July 2006

Notice

The information contained in this document is subject to change without notice.

Hewlett-Packard makes no warranty of any kind with regard to this material, including, but not limited to, the implied warranties of merchantability or fitness for a particular purpose. Hewlett-Packard shall not be liable for errors contained herein or for direct, indirect, special, incidental or consequential damages in connection with the furnishing or use of this material.

Hewlett-Packard assumes no responsibility for the use or reliability of its software on equipment that is not furnished by Hewlett-Packard.

This document contains proprietary information which is protected by copyright. All rights reserved. Reproduction, adaptation, or translation without prior written permission is prohibited, except as allowed under the copyright laws.

Restricted Rights Legend

Use, duplication, or disclosure by the U.S. Government is subject to restrictions as set forth in subparagraph (c) (1) (ii) of the Rights in Technical Data and Computer Software clause at DFARS 252.227-7013. Rights for non-DOD U.S. Government Departments and Agencies are as set forth in FAR 52.227-19 (c) (1,2).

Acknowledgments

UNIX is a registered trademark of The Open Group.

Hewlett-Packard Company
3000 Hanover Street
Palo Alto, CA 94304 U.S.A.

© Copyright 1997–2006 by Hewlett-Packard Company.

1. Overview — MPE/iX Release 7.5**PowerPatch 3 (C.75.03)**

Communicator Summary	6
Chapter 1, Overview — Communicator Summary	6
Chapter 2, Announcements	6
Chapter 3, Technical Articles	6
MPE/iX Patches on HP IT Resource Center	7
Features and Benefits	7
Access Method to the HP IT Resource Center	7
Electronic Digests	8
Patch Installation Tools	8

2. Announcements

MPE/iX Release 7.5 PowerPatch 3	11
End of Support Dates	11
Making the PowerPatch Installation Easy	11
MPE/iX Beta Test Patches Listed On Web Site	11
Obtaining Software Security Patches for your HP Computer System	12
HP IT Resource Center Security-Related Services	12
Subscribing to HP IT Resource Center Security Bulletin Services	12
How to Subscribe	12
If You Discover a Security Problem	13

3. Technical Articles

Enhanced Host-Based DTC Management Functionality	16
Introduction	16
New and Enhanced Functionality	16
Supportability and Other Enhancements	17
OVDTCMgr Features That Are Not Supported	17
Migrating to Host-Based Management	17
The PC and Host Migration Tools	18
More Information	19
Announcing High Availability FailOver/iX for FC Disk Arrays	20
General Information	20
Who Should Consider HAFO	20
Required Hardware and Software	21
Documentation	22
Support of the HP SureStore E Disk Arrays XP12000 and XP10000	23
Support and Documentation	23
Connectivity Options	23
Announcing Limited Support for Ultrium Tape on MPE/iX	24
Hardware and Software Requirements	24
Ultrium Tape Usage Requirements	24
Error Reporting, Diagnostics and Firmware Updates	25
Configuration Limits and Examples for Ultrium Devices on MPE/iX	25
Predictive Changes SYSSTART during UPDATE	27

Contents

TurboIMAGE B-Tree Behavior Clarification	28
Possible Confusing Behavior	28
What to Expect and How to Solve	28

1 Overview — MPE/iX Release 7.5 PowerPatch 3 (C.75.03)

This *Communicator HP e3000* provides general and detailed information on the new and enhanced functionality for the MPE/iX Release 7.5 PowerPatch 3 (C.75.03) as well as information on support, release strategy and installation prerequisites.

This *Communicator* should be used in conjunction with the *Communicator* from Release 7.5. Only information relating to the Release 7.5 PowerPatches 1, 2 and 3 is contained in this document. If you have additional questions beyond the scope of this document, please review the information in the *Communicator* for Release 7.5. This document is available online at www.docs.hp.com.

This MPE/iX *Communicator* describes the following:

- Enhanced Host-based DTC Management Functionality
- High Availability FailOver/iX for FC Disk Arrays
- HP SureStore E Disk Arrays XP12000 and XP10000
- Limited support for Ultrium tape on MPE/iX
- Predictive Changes SYSSTART during UPDATE
- TurboIMAGE B-Tree Behavior Clarification

Communicator Summary

Following are brief descriptions of the articles and chapters.

Chapter 1, Overview — Communicator Summary

This chapter provides a summary of information contained in this manual. It also provides information about obtaining MPE patches from the HP Electronic Support Center.

Chapter 2, Announcements

Important announcements regarding availability of products and services are included in this chapter.

- Introducing MPE/iX Release 7.5 PowerPatch 3
- Additional Announcements from HP
- End of Support Dates
- Obtaining Software Security Patches for your HP Computer System

Chapter 3, Technical Articles

This chapter contains articles about the new and enhanced functionality for MPE/iX Release 7.5 PowerPatches (C.75.01, C.75.02 and C.75.03).

The following articles are included in this chapter:

- Enhanced Host-based DTC Management Functionality
- High Availability FailOver/iX for FC Disk Arrays
- HP SureStore E Disk Arrays XP12000 and XP10000
- Limited Support for Ultrium Tape on MPE/iX
- Predictive Changes SYSSTART during UPDATE
- TurboIMAGE B-Tree Behavior Clarification

MPE/iX Patches on HP IT Resource Center

*by Patch Support Team
Commercial Systems Division*

MPE/iX patches for MPE/iX Releases are available on the IT Resource Center (previously the HP Electronic Support Center) to all customers.

Features and Benefits

The patch access and delivery system benefits all MPE/iX customers with:

- Improved overall communication between HP and customers.
- Provision of useful and timely information for patch justification and decision making.
- Reduced system downtime for known problems.
- Reduction of the turnaround time for patch availability and delivery.
- Close to 24*7 access time.
- Unification of the MPE/iX and HP-UX patch delivery process.

Electronic access to patch information and delivery of patches provide three basic services:

1. Access to patch information in an automated, timely and accurate manner.
2. Electronic downloading of patch information and binaries.
3. Proactive notification of new patches via email.

Access Method to the HP IT Resource Center

To serve customers the IT Resource Center provides World Wide Web access for downloading patches.

Access to the World Wide Web Server

The IT Resource Center is available through World Wide Web. Web access is the easiest, fastest, and most popular method of browsing for patch information and downloading patches. It is more reliable, especially for large patches.

- **U.S. Web accessing address:**
<http://itrc.hp.com>
- **European Web accessing address:**
<http://europe.itrc.hp.com>

Electronic Digests

If you want to keep yourself up-to-date on the latest development of MPE/iX patches, you can sign up for the daily Security Bulletin and weekly MPE/iX Patch Bulletin. Once you have subscribed to these two bulletins, you will receive these digests on a periodic basis via electronic mail. HP IT Resource Center will inform you proactively about newly developed security and GR patches. For more information, refer to the instructions on the IT Resource Center website.

Patch Installation Tools

There are two tools available to install MPE/iX reactive patches, Patch/iX and AUTOPAT. HP recommends the use of Patch/iX for reactive patch installation. Patch/iX has many features and checks to ease and improve the installation process, including:

- A sophisticated patch qualification mechanism to ensure the integrity of your system.
- The ability to perform much of the patch installation process while your system is still up and available to users.
- For more information on Stage/iX or Patch/iX refer to the *System Software Maintenance Manual* for your release. This manual is also available on the following website: <http://www.docs.hp.com>.

You should use AUTOPAT only if you are familiar with its use, and have a good understanding of MPE/iX patch management.

Patch/iX Installation Document Retrieval

These are the steps for retrieving documents regarding Patch/iX.

1. Access the HP IT Resource Center WEB site using the appropriate WEB address for your country.
2. Click on the link, “patch database.”
3. Enter: “ITRC User ID” and “password.”
4. Click on the “MPE/iX” link under “find individual patches.”
5. Click on the link, “MPE Patch Installation and Tools Guide.”
6. Click on the link, “Use Patch/iX or AUTOPAT to install the patch.”
7. Click on the link, “Patch/iX Instructions.”

Patch/iX Version Identification

To ensure you have the latest version of Patch/iX, on your system, do the following:

1. `:HELLO MANAGER.SYS, INSTALL`
2. `:PATCHIX VERSION`
3. Compare this version number (for example, B.01.02) with the latest version available for your release on the HP IT Resource Center Patch/iX download page. If you are running an earlier version than is available, you should download and install the newer one from the download page.

AUTOPAT Installation Document Retrieval

AUTOPATINST is the “DOCID” of the document with instructions to assist you in installing one or more patches needed by your MPE/iX system using the AUTOPAT installation tool.

1. Access the HP IT Resource Center WEB site using the appropriate WEB address for your country.

2. In the Main Menu, click on the link, “Search Technical Knowledge Base.”
3. Enter: “ITRC User ID” and “password.”
4. In the Technical Knowledge Base Home page from the pull down menu, click on “Search By DOC ID” (do not Search by Keyword).
5. In the search field, enter “AUTOPATINST.”
6. Click on the “SEARCH” button.

Create a CSLT Prior to Patch Installation

Before starting any patch application activity, you should always back up your system by creating a Custom System Load Tape and a full backup. This will allow you the flexibility of restoring your system to the previous environment. To create a CSLT, do the following:

1. Log on as `MANAGER.SYS`
2. `.:SYSGEN`
3. `>TAPE`

Disclaimer

CAUTION Hewlett-Packard is not liable for errors occurring during data transmission through the Internet. HP assumes no responsibility for the use or reliability of its software on equipment that it has not furnished itself. Furthermore, for customers without a current support contract with HP, HP is not responsible for answering any questions in regard to the use of this patch delivery process.

2 Announcements

MPE/iX Release 7.5 PowerPatch 3

MPE/iX 7.5 PowerPatch 3 for the HP e3000 is scheduled for delivery in late July 2006.

This proactive patch-set includes defect repairs to improve the capabilities and supportability of MPE/iX 7.5. The improvements it contains are intended to help customers maximize the value of HP e3000 environments as they manage their transitions off the HP e3000 platform.

End of Support Dates

While HP support for MPE/iX 6.0 ended October 31, 2002, MPE/iX releases 6.5, 7.0, and 7.5 will be supported through December 31, 2008.

Please note that although MPE/iX 6.5 and 7.0 are supported through 2008, customers may find it beneficial to upgrade from them to MPE/iX 7.5. The 7.5 release contain changes and improvements – such as defect repair, Native Fibre Channel support for A/N-Class servers, performance and capacity enhancements for high-end systems, and bundled tools for using the HP e3000 with the Internet – that are not all available on earlier releases.

For a comprehensive listing of supported HP e3000 hardware, please go to:

http://www.hp.com/products1/evolution/e3000/news_events/discont/end_support.html

Making the PowerPatch Installation Easy

HP Engineering Services continues to be a major focal point for all your MPE/iX consulting needs. Please contact your local HP support representative for upgrades and installation service.

MPE/iX Beta Test Patches Listed On Web Site

HP is making MPE/iX beta test patches available to our customers who may benefit from installing them before they are made generally available or “GR.”

A beta test or “BT” patch is thoroughly tested in the MPE/iX lab before release. However, it has not completed testing by the customer or customers for whom it was initially created. During this period of customer testing the patch remains in “BT” status so that its distribution can be controlled.

At the web site shown below, you can find a list of all available BT patches by MPE/iX release. There are lists, updated daily, for releases 6.5, 7.0, and 7.5. If you feel your system(s) could benefit from the installation of a “BT” patch, and you have a valid HP support contract, please contact the Response Center to order the patch(es) you would like.

The patch web site is on the JAZZ server at the following URL:

<http://jazz.external.hp.com/src/patches/>

and a link to it can be found on the JAZZ main web page at <http://jazz.external.hp.com>.

Obtaining Software Security Patches for your HP Computer System

Hewlett-Packard would like to make you aware of a special free service provided for all customers of HP e3000 and HP 9000 computer systems. This service gives customers a direct route to Hewlett-Packard for obtaining information relating to the security of their Hewlett-Packard Computer System(s).

Hewlett-Packard issues information on the availability of Software security patches via Security Bulletins to subscribers of the HP Security Bulletin Digest e-mail service, a part of the IT Resource Center (formerly the HP Electronic Support Center). A Hewlett-Packard support contract is NOT required to subscribe to this service to obtain information or security patches. Any purchaser of an HP e3000 or HP 9000 Computer System can make use of the HP Security Bulletin services at no charge.

Customers may also obtain information and Security Bulletin services via the World Wide Web.

A security problem is a software defect that allows unauthorized personnel to gain access to a Computer System or to circumvent any of the mechanisms that protect the confidentiality, integrity or availability of the information stored on the system. When such problems in Hewlett-Packard software are brought to the attention of the company, their resolution is given a very high priority. This resolution is usually in the form of a Security Bulletin which may explain how to correct the problem or describe how to obtain a software security patch that will correct the problem.

Hewlett-Packard has introduced this service as the primary mechanism to alert subscribers to security problems and provide corrections. Hewlett-Packard will not analyze the relevance of any security patch to any individual customer site within the scope of the HP Security Bulletin service. The responsibility for obtaining and applying security patches resides with the customer.

The remainder of this section outlines the various security related services offered by Hewlett-Packard IT Resource Center and the methods for subscribing to and retrieving information from it. It also outlines how you can inform Hewlett-Packard of potential security concerns you may have with your Hewlett-Packard Computer System.

HP IT Resource Center Security-Related Services

HP IT Resource Center offers subscribers the following benefits:

- Receive Security Bulletins automatically when they are published.
- Retrieve the archive list of bulletins issued prior to subscription.
- Download security patches if the subscriber configuration supports it.

Remember, an HP support contract is not required to subscribe to HP Security Bulletin services.

Subscribing to HP IT Resource Center Security Bulletin Services

Once you have placed your name on the subscriber list for future Security Bulletins (see instructions below), you will receive them via e-mail on the day they are issued by HP.

As referenced below, you can also view a list of past Security Bulletins issued in the “HP Security Bulletins Archive.”

How to Subscribe

To subscribe to automatically receive future NEW HP Security Bulletins from the HP IT Resource Center via electronic mail, do the following (instructions subject to change without notice):

1. Use your browser to access the HP IT Resource Center web page at:

<i>http://itrc.hp.com</i>	US, Canada, Asia-Pacific, and Latin-America
<i>http://europe.itrc.hp.com</i>	Europe

2. Logon with your User ID and password (or register for one). Remember to save the User ID assigned to you, and your password.
3. Once you are on the Hewlett-Packard IT Resource Center home page, click on “subscribe to security bulletins and patch digests.” On this page, you can subscribe to many different digest services, including the Security Bulletin Digests.

To review Security Bulletins that have already been released, click on “search technical knowledge base” on the HP IT Resource Center home page. Near the bottom of the next page, click on “Browse the HP Security Bulletins Archive.”

Once in the archive, click on the link to “MPE/iX Security Bulletin.”

If You Discover a Security Problem

To report new security vulnerabilities, send e-mail to

security-alert@hp.com

Please encrypt any explicit information using the security-alert PGP key, available from your local key server, or by sending a message with a -subject- (not body) of ‘get key’ (no quotes) to *security-alert@hp.com*.

3 Technical Articles

This chapter contains the following articles:

- Enhanced Host-based DTC Management Functionality
- High Availability FailOver/iX for FC Disk Arrays
- Support of the HP SureStore E Disk Arrays XP12000 and XP10000
- Announcing Limited Support for Ultrium Tape on MPE/iX
- Predictive Changes SYSSTART during UPDATE
- TurboIMAGE B-Tree Behavior Clarification

Enhanced Host-Based DTC Management Functionality

by John Spitzer, MPE/iX Lab

Introduction

The HP e3000 uses the Data Communications and Terminal Controller (DTC) to provide the hardware and functionality to configure and establish connections to the HP e3000 via Asynchronous Serial ports and X.25/PAD protocols. For the HP e3000 on all supported MPE/iX releases, the configuration and management of the DTCs has been performed by the Open View DTC Manager (OVDTCMgr) workstation running on a PC with Windows 95, or by functions of the DTS subsystem include in FOS with MPE/iX. When the OVDTCMgr manages the DTCs it is known as PC-Based DTC Management and when the HP e3000 host manages the DTCs it is called Host-Based DTC Management. Both PC-Based and Host-Based managed DTCs and HP e3000 hosts can co-exist in any combination within any network.

Due to numerous issues, the Open View DTC Manager solution on the PC has been discontinued as of the end of October 2002. This article describes enhancements made to the DTS subsystem on the HP e3000 in order to provide the functionality needed to continue to support the DTC connectivity required by the HP e3000 users. These added features were available on the OVDTCMgr platform when PC-Based DTC Management was used, but not on the HPe3000 when Host-Based DTC Management was used.

This functionality was first released as two sets of patches. One set of patches was created for release 7.5 and the second set was created for Release 7.0. With this delivery, the patches are now incorporated into MPE/iX 7.5 Power Patch 3 and will be included in all future patches of the subsystems that are affected by the enhancements.

New and Enhanced Functionality

The following is a summary of the DTS subsystem's DTC management features that have been enhanced. All of this functionality was available when using the OVDTCMgr PC-based platform and is now available on the HP e3000 host.

- X.25 System to Systems Switching – You can now configure the DTC to share X.25 connections from one or more cards in a DTC to multiple HP e3000 hosts.
- PAD Switching – Connections from external PAD devices to the DTC can now connect to multiple HP e3000 systems through a shared X.25 card in a DTC.
- PAD Security lists – These lists allow you to configure PAD Security more like the PAD security lists that were available on the OVDTCMgr platform. On the OVDTCMgr platform these were known as the Node Names List and PAD Access List.
- PAD Incoming Security – This table maps a PAD Security list to a set of incoming X.25 PAD addresses to control access to the HP e3000 from PAD devices.
- Non-Nailed TIO devices – You can now configure non-nailed direct connect TIO devices when the system is configured for Host Based Management. Previously, non-nailed direct connect TIO devices were only available when PC-based Management was used on the HP e3000.
- RAFCP and Auto Restart – Routable AFCP on a front end DTC and Automatic Restart of X.25/PAD protocols can now be enabled on the appropriate DTCs.

Supportability and Other Enhancements

To support the enhancements listed above, the following `TermDSM` and `DTCNTRL` functions have also been enhanced:

TermDSM commands:

CONNECT	This command now displays the appropriate information for all supported connection types through both the X.25 and Direct connect cards that are going to any system that has been allowed access from the DTC.
MULTI	This new command allows you start or stop the X.25 and/or PAD protocols on multiple X.25 cards in one or more DTCs with one command.
X25SITE	This new command displays information on X.25 system-to-system connections between HP e3000 systems. This feature displays the same information as the X.25 Site Management feature that was available on the OVDTCMgr platform.

DTCNTRL enhancements:

- All new and changed NMMGR DTS configuration screens are fully supported by Dynamic Configuration.
- To prevent configuration discrepancies that could occur when changes to PAD devices were only partially successful, `DTCNTRL` will now try to verify that the changes to all PAD devices on a card will succeed before proceeding with the changes.

OVDTCMgr Features That Are Not Supported

Some features of the OVDTCMgr workstation are not supported on the HP e3000 host. They are:

Telnet Access Card	This card is long out of support and all of the features provided by this card have other viable alternatives on the HP e3000.
Monitor functions	The following monitor functions are not supported: Describe, DTC Polling, Alarm Logging and Display.
Diagnose functions	The following diagnose functions are not supported: Extended PING.
DTC Tools	DTC Tools – The following DTC tools are not supported: Find Port; In Manage Multiple DTCs, the Delete DTC configuration and paste configurations to DTCs, boards or ports.

Local and Remote DTC Manager Access

Migrating to Host-Based Management

In order to ease the transition from the OVDTCMgr PC-Based solution to Host-Based management, the following features are available and these behaviors occur when your system is updated to the new host-based versions of the DTS subsystem.

- Although it is now an unsupported configuration, the OVDTCMgr platform still is able to manage the DTCs for connection to the HP e3000. HP recommends that you migrate your DTS configuration to Host-Based management at the earliest opportunity.
- When you reboot your system after updating with this release, DTS recognizes that the data in the DTS subsystem of the `NMCONFIG` file is the old format but still creates a valid DTS configuration. DCC displays the following warning message:

```
DCC WARNING P-L, NMCONFIG is previous version. Run NMMGRVER. (DCCWARN 52)
```

The DTS configuration created is identical to what was created prior to the update.

- In NMMGR, if you attempt to display the DTS configuration before running NMMGRVER, a screen states that the DTS subsystem has been updated. From this screen you can launch NMMGRVER to perform the conversion of the NMCONFIG file without exiting NMMGR.
- You use the version of NMMGRVER installed with this release to update the NMCONFIG file to the latest format and then perform a DTS Shutdown and Restart.
- After using NMMGRVER to migrate the configuration file to the latest format, DTS Dynamic Configuration will be disabled until a DTS Shutdown and Restart or system reboot is performed.

The PC and Host Migration Tools

The New Host-Based DTC Management release contains two tools that allows you to migrate a majority of your DTC's configurations from the OVDTCMgr workstation and the PC-Based NMMGR configuration on the host to the new Host-based DTC Management in the NMCONFIG file.

Before you perform the migration, you should read the section "Configuration Issues to Consider Before Migrating" in the updated *Configuring and Managing Host-Based X.25 Links* manual. Review your configuration on the OVDTCMgr platform and any HP e3000 hosts that use those DTCs to determine if there are any configuration changes that you can make to help the process go smoothly. It is likely that you will need to perform some manual changes to the resulting configuration file to create a valid DTS configuration and to reapply your DTC port profile customizations.

These tools and the process for migrating your configuration are fully documented in the updated release of the *Configuring and Managing Host-Based X.25 Links* manual.

The PC Migration Tool

A PC Migration tool has been created that allows you to migrate your DTC's configuration from the OVDTCMgr PC platform to the NMCONFIG file on the HP e3000 host. This tool is incorporated into a patch to the OVDTCMgr. The PC Migration tool is accessed from a new command that has been added to the Manage Multiple DTCs Tool menu.

The OVDTCMgr patch is available as part of this Release 7.5 PowerPatch 2 installation. The patch consists of the following two files:

- READHD45.DTS0000.TELESUP
- EXEHD45A.DTS0000.TELESUP

The full instructions for installing this patch on the OVDTCMgr PC is contained in the READHD45 file.

This tool runs on the PC and creates a text file that contains the NMMGR commands necessary to create an equivalent configuration in the NMCONFIG configuration file of the DTCs that are selected on the PC. The text file that is created is copied to the HP e3000 and read by NMMGR to make the configuration changes to the NMCONFIG file.

The Host Migration Tool

A Host Migration tool has been incorporated into NMMGRVER that merges the configurations of the DTCs in the PC-Based configuration of the NMCONFIG file into the Host-based configuration. This tool is designed to work with the PC Migration tool to create as complete a configuration as possible.

The Host Migration tool can be accessed in two equivalent ways: by running NMMGRVER with the following command parameters:

```
:run NMMGRVER; PARM=77;
```

Or from within NMMGR by pressing the **[Go To Migrate]** key on the Utility screen.

Migrating to Host-Based DTC Management

The migration process has been designed from the view that you will be migrating your HP e3000 host from PC-Based management to Host-Based Management. The process described below assumes that you will be merging the configuration of your DTCs from OVDTCMgr PC and the PC-based tree of the NMCONFIG file into the Host-based tree of the NMCONFIG file. If your system is already configured as Host-based, or you want to retain some DTCs in the Host-based tree of the NMCONFIG file, the process is documented in “Appendix A” of the updated *Configuring and Managing Host-Based x.25 Links* manual.

The Migration process consists of the following major steps. These steps are described in more detail in Appendix A of the updated *Configuring and Managing Host-Based X.25 Links* manual.

1. Run the PC Migration tool on the OpenView DTC Manager PC and select the DTCs that are to be managed on the HP e3000 host. The PC Migration tool will create a file that contains all the NMMGR Maintenance Mode commands needed to create an equivalent configuration on the HP e3000 host.
2. On the HP e3000 host, remove any DTC configurations from the PC-Based configuration in the NMCONFIG file that aren't in use or should not be included in the migration process. Run the DTSValidation and ensure that there are no Validation errors displayed.
3. Change the configuration to Host-based Management and remove all DTCs that may still exist in the Host-Based configuration. Run the DTS Validation and ensure that there are no Validation errors displayed.
4. Transfer the file created on the PC to the HP e3000 host and enter the following commands to use the file as input commands to NMMGR to create the configuration in the NMCONFIG file.

```
:file nmmgrcmd=<cmdfile>  
:nmmgr
```

Where <cmdfile> is the file that was transferred from the OVDTCMgr PC.

5. Run the Host Migration tool integrated into NMMGRVER and merge the PC-Based DTCs configured in the PC-based configuration into the Host-based configuration.
6. Create or modify any profiles that have been assigned to DTC devices if you want to apply customization to the DTCs devices. The profile names assigned by the migration process will either be a default name assigned by the PC Migration tool or the profile name that was assigned to the port in the PC-Based Configuration.
7. Validate the NMCONFIG file and perform any changes needed to resolve any configuration discrepancies that are found.
8. Use DTCCNTRL to perform a DTS Shutdown and Restart.

More Information

More information on the change to the DTS subsystem's configuration in NMMGR is available in the updated *Configuring and Managing Host-Based X.25 Links* manual that is available online from:

<http://www.docs.hp.com/en/36939-90057/36939-90057.pdf>

or from the JAZZ website at:

<http://jazz.external.hp.com/papers/manuals/36939-90057.pdf>

Announcing High Availability FailOver/iX for FC Disk Arrays

by *Jim Hawkins, MPE/iX Lab*

General Information

At no charge, High Availability FailOver/iX (HAFO or HAFO/iX) is now available for HP e3000 systems connected to many of HP's VA and XP family Fibre Channel (FC) disk array products. Support is offered for customers with HP e3000 A/N-Class systems running MPE/iX 7.5 using the A6795A 2Gbit FC-HBA and also for customers with HP e3000 S9xx systems running at least MPE/iX 7.0 using the A5814A-003 SCSI-FC Router. This greatly expands the coverage of the HAFO product which until recently supported only the SCSI XP256 (SCSI XP256 remains supported with these changes).

Once the HAFO software is installed, the user configures each disk LDEV with a primary data path and an alternate data path. In a normal state, data is routed through the primary path while HAFO software continually monitors disk I/O reply messages for failed components. HAFO is designed to detect the following event types:

- Hung I/O
- Failed disk controller
- Failed I/O host device adapter card
- Failed connection component (cables, switches, routers)

When these events are detected the HAFO software will "failover" to the alternate data path. That is, all subsequent I/O is sent to the configured alternate data path. No application or higher level MPE/iX Operating System component should experience an abnormal event. All I/Os complete as normal using the alternate data path and alternate array controller.

In the event of a failover, the system operator is notified via an MPE/iX console message. This is a "repeater" type message. Repeater messages are repeatedly sent to the console at approximately five minute intervals until a REPLY command is used to acknowledge the message. In addition to the console message, the failover event also causes I/O type log records to be written into the MPE/iX system log file.

Upon repair of the failed component, the system operator may switch the LDEV back to the primary path to restore HAFO protection for that device.

NOTE To prevent an uncontrolled series of repeated failover events HAFO does not allow automatic "fail back" from alternate to primary path

Who Should Consider HAFO

HAFO is for customers using disk arrays who want protection against failure for the following components of the I/O subsystem:

- I/O Host Bus Adapter (HBA)
- Cabling
- FC Switches
- SCSI-FC Routers
- Disk Controllers

CAUTION Before deploying HAFO, system disk I/O performance should be analyzed. Those systems with disk I/O bottlenecks (long disk queues and/or I/O completion times greater than a few seconds) are not good HAFO candidates as false failover events may be seen.

NOTE Those customers using Cluster/iX to protect their MPE/iX disk volumes may NOT use HAFO/iX on these same volumes. Further, Cluster/iX and HAFO/iX protected volumes may not share an HBA.

Required Hardware and Software

Required Hardware

- HP e3000 (each HAFO connection requires a pair of HBAs)
 - S9xx
 - A28696A NIO F/W SCSI Card
 - A5814A SCSI-FC Router
 - A-Class, N-Class
 - A6795A 2Gbit FC HBA
- Supported FC Multi-port Disk Array Products (each HAFO connection requires a pair of ports)
 - VA7410
 - XP48 and XP512
 - XP128 and XP1024
 - (SCSI XP256 remains supported)

Minimum Required Software

MPE/iX 7.0 (for HP e3000 S9xx)

MPE/iX 7.5 (for HP e3000 A/N-Class)

MPEMXL5 (I/O Core Patch for BOTH 7.0 and 7.5) (or superseding patch)

MPEMXK9 (HA Utilities Patch for BOTH 7.0 and 7.5) (or superseding patch)

Hardware that is NOT supported

- Any Arrays not listed above including, but not limited to
 - VA7100, VA7110 (supported on MPE but not for HAFO)
 - FC-XP256, VA7400 (never supported on MPE)
- A5814-001 Distancing Router (direct connect to XP48/512)

Documentation

Please refer to <http://docs.hp.com/> for the new edition of the HAFO manual:

High Availability FailOver/iX Manual (MPE/iX 7.0, MPE/iX 7.5) Edition 2, date code E0803, Part Number: 32650-90911 (“.pdf” only)

The previous version of the manual still applies to MPE/iX 6.5 customers with SCSI XP256: “High Availability Failover Utilities Configuration Guide” (Part No. 32650-90899)

Additional information on HAFO, HP e3000 High Availability products, disk array utilization and MPE specific FC configuration information can be found in the “High Availability” section of the CSY external web site: http://jazz.external.hp.com/mpeha/papers/index_papers.htm

Recommended items for customers deploying HAFO and FC disk arrays include:

Table 3-1

High Availability FailOver/iX	(Web based training slide show with audio)	http://jazz.external.hp.com/mpeha/papers/HAFO_training_session/HAFO_training_session.html
Router White Paper	(Important information for A5814A-003 SCSI-FC Router)	http://jazz.external.hp.com/mpeha/papers/router_paper01.htm
MPE Disk Performance White Paper	(General discussion of disk performance issues)	http://jazz.external.hp.com/mpeha/papers/off_white_2004.html
How-To Papers	(Other HA related subjects)	http://jazz.external.hp.com/mpeha/howto/index_howto.html

Support of the HP SureStore E Disk Arrays XP12000 and XP10000

by Dave Black, MPE/iX Expert Center and Jim Hawkins CSY Lab

This article contains information on the support and configuration of the HP SureStore E Disk Arrays XP12000 and XP10000. These are part of the overall XP family of arrays. The XP12000 is the high-end part of the XP12000/XP10000 pair. The XP10000 is a smaller, repackaged version of the XP120000.

For details, refer to <http://spock.corp.hp.com/> for MPE/iX “Streams” connectivity documents. The “SPOCK” site also provides a jumping off point for all XP documentation, both externally and internally focused.

Support and Documentation

Device installation and support is provided by HP. For detailed information on the support and configuration of the arrays, refer customers to the relevant product manuals. <http://www.hp.com/go/storage> is the home page for HP storage devices and contains links to the XP products. HP e3000 and MPE/iX specific implementation information for disk arrays and related products is available at <http://jazz/external.hp.com/mpeha/>.

Connectivity Options

Fibre Channel Support

Preferred and recommended for A-Class and N-Class HP e3000 systems

Direct fibre channel support is only available on the A400/A500/N4000 systems through the A6795A card.

Supported on Release 7.5 + PPT 2

SCSI -- Fibre Channel Support

Preferred and recommended for S9xx NIO HP e3000 systems

Supported on Releases 7.0 PowerPatch 2 and 7.5 + PowerPatch 2

Support via a SCSI-to-fibre-channel connection is only available through a Fibre Channel Router A5814A-003.

Supported systems include S9xx (9x9, 99x, 9x8, etc).

Supported IO cards include A28696A NIO (3728 or 3944 FW)

(A/N-Class customers may use A4800A, A5159A and A5159B PCI, but Native FC A6795A is recommended).

Announcing Limited Support for Ultrium Tape on MPE/iX

by *Jim Hawkins, MPE/iX Lab*

The purpose of this article is to document the limited support offered for Ultrium Tape Devices (a.k.a. “LTO”) on MPE/iX.

The primary considerations are outlined below. Items #3 and #4 are unique to Ultrium Tape Devices and represent a departure from traditional MPE/iX tape device support.

1. System and connection types: A-Class and N-Class, LVD-SCSI only.
2. O.S. software: MPE/iX 7.0 or 7.5 with appropriate version of patch MPEMXJ3.
3. Supported software: Only for use with certified 3rd party back-up solutions.
4. Diagnostic support: Very limited, requires access to Windows or HP-UX system with LVD-SCSI HBA and current version of HP Storage Works Library and Tape Tools. Some diagnostic activities may require removing the tape device from the HP e3000.

More in depth discussion of these items along with configuration details follows.

Hardware and Software Requirements

MPE/iX support of Ultrium 215 and 230 devices is limited to parallel LVD-SCSI connections only. Thus, these devices may only be connected to HP e3000 A-Class and N-Class systems running MPE/iX 7.0 or 7.5 Release. In addition, patch MPEMXJ3, version “A” for MPE/iX 7.0 or version “B” for MPE/iX 7.5, must be installed for the device to be supported. Finally, on 7.0 only, patch MPEMX74 “A” should also be installed.

Only those HP Ultrium Tape devices sold for use with HP-UX PA-RISC server systems will be supported. There are variations in firmware for the many Ultrium devices on the market; only devices with the firmware for HP-UX server systems will be supported. More on Firmware below.

Ultrium Tape Usage Requirements

Ultrium devices will only be supported for access/usage by certified 3rd party supplied back-up products; certified products are currently limited to:

- BACKUP+/iX (ORBiT Software Inc., <http://www.orbitsw.com/>)
- HiBack® (Mount10 Group, <http://www.mount10.com/>).

Ultrium Tape devices are NOT supported for any other traditional MPE/iX tape functions including, but not limited to: System boot, SYSGEN, HP Store/Restore, HP TurboStore, general file system access, user logging, FCOPY, Sherlock diagnostics, etc. These restriction are in place due to incompatibilities between MPE/iX tape usage patterns and Ultrium implementation assumptions which can lead to unacceptably poor performance. In most of these cases, there are no actual blocks in place to prevent using Ultrium; nevertheless, such usage is NOT supported.

There is one small exception: The program `devtool.pub.sys` and the command file `devctrl.mpexl.telesup` may be used to load/unload media but it will NOT support turning compression on/off for Ultrium. HP Ultrium incorporates “intelligent” compression that prevents attempts to compress data that is already compressed so there is no need to explicitly turn device level (hardware) compression on or off.

Error Reporting, Diagnostics and Firmware Updates

MPE/iX logs all Ultrium Tape device errors and checks conditions to the system log files as with other SCSI tapes. System Log files can then be examined with LOGTOOL or cstm's logtool utility. Similarly, all standard tape console messages such as AVR tape mount or cleaning cartridge prompts can be seen. However, MPE/iX cstm (a.k.a. MESA) diagnostics, (like HP-UX cstm) do NOT allow Ultrium access to functions such as "expert tools" or "firmware update."

Most diagnostic support for Ultrium drives comes from HP Storage Works Library and Tape Tools (a.k.a. LTT). LTT does not run on MPE/iX; therefore in some diagnostic scenarios the Ultrium may have to be removed from the HP e3000 and connected to a host running LTT. For details on LTT, please reference the HP corporate web site *www.hp.com*. Currently "HP StorageWorks Library and Tape Tools" web page may be found at:

<http://h18006.www1.hp.com/products/storageworks/ltt/index.html>

Firmware update can be accomplished through Firmware Upgrade Tape (FUP). The Firmware Upgrade Tape (FUP) creator is part of the HP Storage Works Library and Tape Tools. The FUP creator must be run on Windows, HP-UX or Linux. Once a FUP is created it can be used to update Ultrium devices connected to the HP e3000. More information can be found at the following web sites:

HP External: "HP Ultrium - Firmware Upgrade Instructions for HP Standalone External, Internal and M-drive Ultrium Tape Drives"

<http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp/objectID=lp50219>

HP Internal: NSS Nearline storage "HP StorageWorks Library and Tape Tools - Firmware"

http://hpclib1.gr.hp.com/customercare/Technicalsupport/diagnostics/LTT_firmware.htm

Ultrium device firmware should selected for devices to be compatible with HP-UX Server Systems. Current firmware levels are:

- Ultrium 215, firmware revision N26D
- Ultrium 230, firmware revision E32D

Configuration Limits and Examples for Ultrium Devices on MPE/iX

Physical connections are to be made only to LVD-SCSI Host Bus Adaptors. LVD-SCSI terminators must be used for devices to function at rated speeds. HP recommends only ONE Ultrium Tape device per SCSI bus for maximum performance. No more than TWO Ultrium Tape devices per SCSI bus will be supported. An Ultrium device must never share a SCSI bus with any other SCSI peripheral type.

You may configure an Ultrium tape LDEV via SYSGEN or IOCONFIG as you would any other SCSI tape device. On 7.0 with MPEMX74 you should use device ID=DLT. On 7.5 you may use device ID=LTO or ID=DLT. (Using device ID of LTO or DLT assigns the scsi_tape2_dm driver to the device. This driver supports Ultrium, DLT and other, "non-DDS" tapes. The driver, completed by MPEMXJ3, will detect Ultrium devices and automatically make the appropriate SCSI mode page settings.)

Ultrium devices are configured as standard SCSI type devices and so require a "pseudo" device to be configured as do all other SCSI devices on MPE/iX

Configuration Example:

Given the following output from “ISL> ODE RUN MAPPER2”

```
0/6          Elroy PCI Bridge                DH   782H AH   0   0
0/6/2/0      Symbios SCSI Controller
0/6/2/0.3.0  Ultrium (LTO) 1-SCSI Tape drive  -   -   -   -   E32D
```

The following SYSGEN (IOCONFIG) commands would be used:

```
sysgen> ap 0/6          pat_pci_bc
sysgen> ap 0/6/2        pci_device
sysgen> ap 0/6/2/0     A5149A
sysgen> ap 0/6/2/0.3  PSEUDO
sysgen> ad 19 0/6/2/0.3.0 LTO
                        |||
```

(ID of DLT may be used on 7.0)

To confirm, use the “list path” command. The last three entries should show:

```
sysgen> LP
. . .
PATH: 0/6/2/0          LDEV:
ID: A5149A            TYPE: DA
PMGR: PCI_SCSI_DAM    PMGRPRI: 6
LMGR:                 MAXIOS: 0

PATH: 0/6/2/0.3       LDEV:
ID: PSEUDO            TYPE: DA
PMGR: TRANSPARENT_MGR PMGRPRI: 6
LMGR:                 MAXIOS: 0

PATH: 0/6/2/0.3.0     LDEV: 19
ID: LTO                TYPE: TAPE
PMGR: SCSI_TAPE2_DM   PMGRPRI: 10
LMGR: LOGICAL_DEVICE_MANAGER MAXIOS: 0
```

Predictive Changes SYSSTART during UPDATE

by Gary Robillard, Predictive Support

Due to some customer sites having multiple startup directives in `SYSSTART.PUB.SYS`, the job that installs Predictive has been modified to recognize this. Previously, this Predictive job would just add the "STREAM JPSMON.PRED.SYS" line to the end of `SYSSTART`. Now, the job modifies the `SYSSTART` file as follows:

1. Gather STREAMs device and printer queue for STREAMs and OPENQ commands if needed.
2. If `SYSSTART.PUB.SYS` does not exist, a new `SYSSTART` file is created on ldev 1 with the following contents:

```
STARTUP
**
WARMSTART
OPENQ LP
STREAMS 10
STREAM JPSMON.PRED.SYS
**
COOLSTART
OPENQ LP
STREAMS 10
STREAM JPSMON.PRED.SYS
****
```

3. If a WARMSTART, COOLSTART, RELOAD or UPDATE section exists and has commands, AND there are no other STREAM commands AND there are no STARTSESS to OPERATOR.SYS commands, then do not modify the `SYSSTART` file.
4. If there are STARTSESS commands but no STARTSESS to OPERATOR.SYS, then do not modify the `SYSSTART` file.
5. The command `STREAM JPSMON.PRED.SYS` is removed from the STARTUP section and added to the WARMSTART and COOLSTART sections. If no WARMSTART and COOLSTART sections exist, they are created and contain these commands:

```
**
WARMSTART
OPENQ LP
STREAMS 10
STREAM JPSMON.PRED.SYS
**
COOLSTART
OPENQ LP
STREAMS 10
STREAM JPSMON.PRED.SYS
****
```

If the file `NOSYSST.PRED.SYS` exists, it prevents the Predictive job from doing any `SYSSTART` file processing during installation. Therefore, if you do NOT want the "STREAM JPSMON.PRED.SYS" command added to your `SYSSTART` file, create the `NOSYSST.PRED.SYS` file with a build command.

```
BUILD NOSYSST.PRED.SYS;DISC=1
```

TurboIMAGE B-Tree Behavior Clarification

by Tien You Chen, MPE/iX Lab

Possible Confusing Behavior

TurboIMAGE has supported B-Tree indices since C.07.00. Even though a user can create a B-Tree index only on the master data set's key item, s/he can perform index searches using all of its corresponding detail data set search items as well. Users can now call DBFIND to perform a generic key search on a master data set, then chained DBGETs to return all the qualified records. Confusion arises when a user calls DBFIND on a master data set but, before or between the chained DBGETs of those qualified records, s/he calls another DBFIND on a detail data set using a search item linked to the master currently being accessed chained. This DBFIND will reposition the chain pointer on the master. As a result the user may get an 'end of chain' status for the next DBGET to the master data set. Since these two DBFINDs are finding against two different data sets, the user is amazed at the interference between these two.

What to Expect and How to Solve

Because only one KSAM/iX file is attached to each master data set, all B-Tree access for related detail data sets also goes, via the master data set, to the same KSAM file. Since there is only one logical record pointer in the KSAM file, a new DBFIND, which positions the logical record pointer, affects the current reading. In addition, the internal runtime data structure, though allocated one per data set, is still affected. Therefore, even if the second DBFIND on the detail data set is not a B-Tree DBFIND, many flags in the runtime data structure are reset. The next DBGET to the master data set acts as though there was no previous B-tree DBFIND to the master.

This combination of access methods, mixing DBFIND/chain DBGET to a master with DBFIND/chain DBGET to a detail using a path to that same master, is not common. We suggest the user call a second DBOPEN to handle the second DBFIND. However, please remember the second DBOPEN is needed only when calling DBFIND on a detail chain while still performing chained DBGETs on the related master data set.